

SPÉCIALISTE BOITE AUTOMATIQUE





www.bvautomatic.fr

05 34 28 01 15

TEST, CONTROLE & RÉPARATION
DES BLOCS HYDRAULIQUES

TEST ELECTROVANNES

SERVICES DÉDIÉS AUX PROFESSIONNELS
RE-MANUFACTURATION



Test Plate AW 55-50SN

Test Plate AW TF80

Test Plate AW TF81

Test Plate AW TF70-TF80 Mk2

Test Plate AW 60-09G

Test Plate AW 60-09D

Test Plate Mercedes 722.6

Test Plate Mercedes 722.9

Test Plate ZF 6HP19-26-32 (Gen 1)

Test Plate ZF 6HP21-28-34 (Gen 2)

Test Plate ZF 8HP45-70

Test Plate Chrysler 62TE

Test Plate Chrysler VW DSG-02

Test Plate Renault / Peugeot / Citroen DP0-AL4

Test Plate GM 5L40E

Test Plate JATCO JF506E

Test Plate Nissan RE5R05A

Test Plate Toyota U240E-U250E

Test Plate Toyota U660E-U760E

Test Plate Toyota A750-A760

Test Plate Mitsubishi / Hyundai / KIA F5A51

Solenoid Adapter plate for HT-VBT machine testing

B - 55-50

C - TF60 - TR60 - TF80

E - TR80 - TF70 - TF80S - TF80 Mk2

F - Mercedes 722.6 - 722.9

I - DSG-02 (6 Speed)

L - RE5R05A

M - U150E-U250E

N - U660E

O - DSG-0AM (7 Speed)

P - GM5L40E

Q - JF506E

U - V5A51 - V4A41 - F4A41,42,51 - F5A51